

Subject to Collision damage on starboard bow being

ADDRESS "REGISTER, GLASGOW."

TELEPHONE: CENTRAL 6490 (4 LINES).

6

Lloyd's Register of Shipping.

95, Bothwell Street, Glasgow, C.2.

1st June, 1937.

Dear Sir,

With reference to your letter of the 29th ultimo respecting the Steamer "MANIPUR", I beg to acquaint you that the defective rivets have now been received from the Society's Liverpool Office and have been handed to Mr. Lewis who will give the matter attention and forward his report in due course.

I am, Dear Sir,

Yours faithfully,

L. H. Windsor
Secretary to the
Glasgow Committee.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

W53-0042

76

with

W53-0052

