

Received by Chief Ship Surveyor 24.7.16

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Motor Vessel Hebe* Rpt. *Ret* No. *10130*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor *1<sup>st</sup> Sub*

The Amsterdam Surveyors should be informed this vessel is proceeding to their port where the machinery is to be fitted & that in order to complete the Survey the following repairs to be done <sup>viz</sup> the motorroom skylight require to be putted up, pillars to be fitted in motorroom to sink machinery, a power anchor (stockless) <sup>cut of 14</sup> 20.10 + 45 fathoms of 1 3/16 chain cable to be supplied & marks thereon compared with Certificate of test, & the foreboard to be verified.

They should be requested to give this case attention & to report in due course on form 8 so that the classification of the vessel may be completed.

*M*  
25.7.16



© 2021

Lloyd's Register Foundation

W530-0023