

Steam Trawler "CHERITON"

Owners: The Boston Deep Sea Fishing & Ice Co., Ltd.

In November last the Aberdeen Surveyors reported this vessel examined on account of grounding, and a number of repairs were recommended to be carried out.

The Owners, decided, however, to have the vessel broken up, and the repairs were not effected.

The Surveyors paid two visits to the vessel, and a fee of £5-5-0 was charged.

The Owners now state that in their opinion the above charge is on the high side, and they ask whether it could be reduced to £3-3-0.

The Aberdeen Surveyors suggest that £3-3-0 might be accepted.

It is submitted for consideration whether the fee might be reduced to £3-3-0.

17.3.39.



© 2019

Lloyd's Register
Foundation

W531-0060