



Lloyd's Register of Shipping.

14, Cross-shore Street,

Greenock, 13th March, 1937.

LLOYD'S REGISTER
RECEIVED
15 MAR 1937
ARSD.
LONDON

Dear Sir,

I enclose the Freeboard Certificate and Certified copy for the S.S. "DHOON GLEN", Official Number 145,447. This ship is presently undergoing repairs at Port-Glasgow and the Special Survey 2nd No. 1 - due 8-37, is commenced, and well advanced, but will not be completed at this time. The name of vessel has been changed at this time to "RUMORE", and new certificates are required in consequence. An annual freeboard survey only is being held at this time and Form C.11(a) will be forwarded on completion of Repairs. Freeboard verification Report 12(a) is forwarded herewith together with original freeboard report ^{4 C.H.} 11b. On checking items on ship with this latter report it was noted that the soil pipes from W.Cs. were now led each through shell below freeboard deck with automatic non-return valve at shell.

I shall be pleased if you will kindly forward new Freeboard Certificates in time for vessel's probable sailing on Wednesday next, 17th instant.

I am, Dear Sir,
Yours faithfully,

The Secretary,
LONDON.

© 2019
Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor
(Freeboard).

15 MAR 1937

REQUESTING EARLY REPLY.

J.P.

*scribble in forward
letter the document
both
10/3/37*

*His submitted new cert. to the Chief Surveyor for issue for issue
Survey is completed
Rpt 9a now attached*

*John
Y.S.
15 MAR 1937*



© 2019

Lloyd's Register
Foundation

Suggested Reco

Particular
Casualty

Classing Comm