

S.S. "RUMORE"

It is submitted the Solicitor to the Board of Trade be informed that as stated in the Secretary's letter of 1st instant, no sketch is available in this Office shewing the details of the strengthening to the flat of the bottom forward.

In the First Entry Report, however, the Surveyor states that the midship thickness of the bottom and side plating has been maintained all fore and aft, which makes it clear that item (3) mentioned in the Secretary's letter has been complied with. With regard to items (1), (2) and (4) no space is arranged on the First Entry Report for the reporting of these, which are covered by the general statement appended by the Surveyor at the end of the report which reads as follows:-

"This vessel has been built in accordance with  
"the approved plans, and in general conformity  
"with the Rules of the Society".

*Dis. 2.2.39  
Amtd. 6.2.39*

*S.E.R.*

*6.2.39*



© 2019

Lloyd's Register  
Foundation

W532-02S2