

29/9/10.

Received from Chief Surveyors

AE Stl. J.S.S. "Kursk"

Report

Gls.

No. 29327.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been
red and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case
at the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Entry.

When due

+ 100A1 ("Steel")

3 Dhs. (upper stl. Leaks) 2nd deck (stl. W.S.)

W.B. = cell DBa 106' v E 47' f 184' 897t. F.P.T. 57t. A.P.T. 29t.

FK. 7BH. Lem. Lloyds A.C.P. P. 75' Shad. deck 40' B. 203' F 84'

M

RH
29/9/10



© 2020

w 534-0353
Lloyd's Register
Foundation