

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

"CHYEBASSA".

Rpt.

Cal.

No.

10417.

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endorsement."—Extract from Sub-Committee's Report, 24592.)

SPECIAL SURVEY OF ~~ENGINES AND/OR BOILERS PARTLY HELD FOR S.S.~~ No.

due 8,38 , partly held 8,38

the together advanced and the following repairs effected (due to ing.

is proposed to complete the survey-not stated.

is submitted that ~~this proposal merits approval and~~ the vessel is to remain as classed, and WILL BE eligible for the record when the survey has been completed.

following remains to be done to complete the Survey

line the three after boilers and repair the centre furnace of the ler.



© 2020
21.10.38.

Lloyd's Register
Foundation

W535-0034