

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.")

Transverse No.

Depth "d"

Framing: Table No.

Description

Longitudinal No.

Proportions

$$\frac{\text{Length}}{\text{Depth}} =$$

Deck Sheerstrake

This vessel appears to have been built in accordance with the

Rules and the approved plans, and it is submitted she is eligible to

be classed  $\pm$  100 A.1. (Stat) as recommended. $\pm$  100 A.1. (Stat)

1/2 (pt. in. - pt. out)

W.B. Bull DBA III u 524 f153 8316 F.P.T 1396 A.P.T 1476

F.K. G.B.H. Gmn. Lloyd's at 60 P23 B99 F36

M

L.B.H.

5/5/10

© 2020



W 539-0201 Register  
Foundation