

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report *9 Aug* 19*04* When handed in at Local Office *11 Aug* 19*04* (Received at London Office *THUR. 11 AUG 1904*)
No. in Reg. Book. *1471* Survey held at *West Hartlepool* Date, First Survey *7 Aug* 19*04* Last Survey *9 Aug* 19*04*
on the Machinery of the Wood, Iron or Steel *Steamer "Stork"* Master *W. J. M. M.*
Tonnage { Gross *2050* Net *1904* Vessel built at *Stockton* By whom *Ropner & Son* When *1904*
Engines made at *Middlesbrough* By whom *Richardson & Wigham* When *1904*
Boilers, when made (Main) *1904* (Donkey)
Owners *General Steam Navigation Co* Port *London* Voyage *Stockton*
If Surveyed Afloat or in Dry Dock *Any Service* (State name of Dock.)
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. *1471* Port *Stockton*

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *✓*Do. " Donkey " " " *✓*If this was not done, state for what reasons? *✓*And what parts of the Boilers could not be thus thoroughly examined? *✓*Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *✓*Did the Surveyor examine the Safety Valves of the Main Boiler? *✓*

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? *✓*

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? *✓*

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? *✓*

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? *✓*

, and of the Donkey Boiler?

Has the propeller shaft been drawn and examined at this time? *No*

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? *new*If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *✓*

*The Propeller shaft stern bush and sea connection
were seen good. Propeller good.*

General Observations, Opinion, and Recommendation:— *This case is submitted*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,00, B.&M.S. 9,00, or L.M.C. 9,00, 140 lb., F.D., &c.)

For the information of the Committee.

Office or Registration Fee (per Sec. 27).....	£	:	Fees applied for
Survey Fee (per Section 28).....	£	:	19
Special Damage or Repair Fee (if any).....	£	:	Received by me,
(per Section 28).			
Travelling Expenses (if chargeable).....	£	:	19

James James
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

FRI. 19 AUG 1904

Committee's Minute

Assigned



© 2020

Lloyd's Register

W529-0273

It is submitted that
this vessel is eligible to
remain as CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Q.M.
11.8.04

SHIP'S RECORD

NAME OF VESSEL

REG. NO.

DATE OF REG.

REG. OFF.

W

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.