


I have to state that the screw shaft is fitted with a continuous

S.S. "Kalgora"

Sp. 15977.

It is concluded that the screw shaft
is fitted with a continuous cover, but
this should be confirmed by the West-
Hartlepool Surveyors.



© 2019

Lloyd's Register
Foundation

31/5/22.

W54-0012