

*haimoa*

For the information of Surveyors and the Committee only.

Received at

Office,

25 JUN 1935

# Lloyd's Register of Shipping.

(Report on Machinery, No. *92664*)

Port *Inver*

No. *V 2076*

## ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by *Messrs John R. East & Co.* of *Burdonald, Glasgow* for the Engines or Boilers No *R. 105/35* being *Repaired* ~~constructed~~ by *Messrs North Eastern Marine Engineering Co Ltd* of *Wallsend* have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to

*Wallsend*

Stamp Mark.

LLOYD'S TEST,

*240* lbs.

No.

*27-3-35*

*S. J. Pearson*

*Glasgow*

and  
Description.

*Four 2" Single Spring Safety Valves.*

lic Test:  
per square inch.


*Four Hundred and Forty*

Tests, if any.

✓

When Inspected.

*27<sup>th</sup> March 1935.*



© 2019

Lloyd's Register  
Foundation

W54-0099

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Stockless, state Mechanical Tests