

Steel T.S.S. "Groya"

Bel.

8892.

see letter
rec. 19/4/23.

It is concluded four web frames are fitted in the Boiler space as shown on the approved plans, and not three as reported, but the Surveyors should be requested to state if this is so.

for 13/4/23



© 2019

Lloyd's Register
Foundation
W540-0171