

Amadale Castle Report No. 21318

Steel screw steamer No. 424 building by Messrs. The Fairfield S.B. & E. Co., Lim., at Glasgow, for the Union-Castle S.S. Co., with a view to class 100A1.

Rule dimensions ; 567.92 x 64.26 x 43.85

The bower anchors required by Table 22 are as follows:-

| | | |
|--------------------|---------------------|----------------------|
| 1st Bower | 117½ cwt. stockless | |
| 2nd " | 117½ " | " |
| 3rd " | 100 " | " |
| Collective weight | 335 " | |
| With Stream anchor | 36 ex stock. | Kedge anchor 19 cwt. |
| Stock | 9 | Stock 4. 3. 0 |
| | 45 cwt. | 23. 3. 0 |

At the desire of the Owners the following equipment was approved by the Committee instead of the three bowers required by the Rules, viz:-

| | |
|------------------------------------|---------------------|
| 1st Bower | 117½ cwt. Stockless |
| 2nd " | 117½ " |
| 3rd " 72 cwt. (Rodgers) ex stock = | 90 including stock |
| 4th " " " " = | 90 " " |
| Collective weight | 415 |

The anchors are supplied as follows:-

| | |
|---|---------------------------------------|
| 1st Bower | 117. 2. 21 Stockless. |
| 2nd " | 117. 0. 10 " |
| 3rd anchor 71. 2. 22 stock 18. 1. 11 = | 90. 0. 5 including stock. |
| 4th anchor 71. 2. 0 stock 18. 0. 13 = | 89. 2. 13 " " |
| Collective weight | 414. 1. 21 |
| with Stream anchor 36. 3. 0 stock 9. 0. 22 | and Kedge 19. 1. 21 stock 4. 2. 15 |
| 45. 3. 22 | 24. 0. 8 |

© 2020 Lloyd's Register Foundation

W542-0116/2

and 3rd and 4th Dk. 10592.74
Total under Upper Dk. 10592.74
of Poon 32.13

Half Breadth (moulded) 32.13

Year of appointment

It is submitted that as the weights of the bower anchors supplied are only slightly less than those approved by the Committee on the 28th August, 1902, and the total weight of the anchors is much in excess of the Rule requirements, the equipment as supplied is worthy of the favourable consideration of the Committee.

J.M.

C.B.

27.10.03.

TUES. 27 OCT 1903

approved
W

22.10.03

Wed. 27th

1 plan.



© 2020

Lloyd's Register

WS42-0116 2/2

WS42-0119

Width of main deck, no. and spacing

Na. Side Stingers

Angle on ditto

To Plating

Deck. Material and thickness

Leak