

F.E.

Received by Chief Ship Surveyor 19.5.05

Received from Chief Ship Surveyor

VESSEL'S NAME *St. S. "Pacware"*

Report *Bel.* No. *5906*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .		
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm 100 A 1$  ("Steel") as recommended.

$\pm 100 A 1$  ("Steel")

4 Ds (Set - UWS)

W. B = Cell DB a 79' in E + B 65' f 131' 770 t Tanks at sides of Tunnel 31' P856875t

FK 4 BH only Cam. Lloyd's A & CP F 43'



© 2020

Lloyd's Register

W 542 043

50,44

Quarter 'tween Dks.,	"	"	"	"	"	Deck. Material and thickness
in Hold	"	"	"	"	"	Forecastle Deck Stringer Plate, b'dth & th'kns
FRAMES In Hold	"	"	"	"	"	Angle on ditto