

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

4th December, 1936.

Dear Sir,

With reference to your First Entry Report No.1510 on the electrical equipment of Messrs. A/B Oresundsvarvet's Yard No.41, I have to inform you that the test sheets for the generators and motors attached to your report do not all give the requisite information, and the records in some cases are missing. These are:-

(1). Test records are missing for

12 KW auxiliary generator.
2 - 2½ HP oil separators.
2 - 10 HP ventilation fans.
10 HP oil fuel transfer pump.

These records should be obtained and submitted for approval.

(2). The test record for Messrs. Svenska Elektromekaniska Industriaktiebolaget's machine No.106733 does not contain details of all the tests required by the Rules. This machine is a 9 HP bilge pump motor, and details should be submitted to show that it meets with the requirements of the Rules.

(3). The test records for Messrs. A.S.E.A. machines 587108-109 are also lacking in the required information. It is concluded that one of the above is for a 1HP refrigerator circulating pump. Messrs. A.S.E.A. are aware of the Society's requirements.

~~2~~
COPY.

as similar cases have been dealt with previously, and they should accordingly be asked to furnish information which would show that the motor complies with the requirements of the Rules.

I have also to request that you will forward your Report Rpt.40 in respect of the generator engines.

I am, Dear Sir,

Yours faithfully,

Secretary.

O.A.Sunden, Esq.,

MALMO.



© 2020

Lloyd's Register

W544-0135 1/2
Foundation

DOU
Sol