

S.S. "BOETON" Nwc.Rpt.No.14597

The First Entry Report on this vessel's machinery was received on the 21st January. To complete the survey for classification the main boiler and superheater safety valves required to be adjusted.

When on a trial trip the vessel stranded at Hartlepool. She was re-floated and all the machinery has been again examined and found to be in good order. 4 blades of the propeller have been renewed. But the safety valves still remain to be adjusted and easing gear fitted and this will be carried out on arrival at Amsterdam.

*It is submitted that
this vessel is eligible for
THE RECORD, LMC 2,13*

S2,13 FD

Subject to the safety valves being adjusted
and easing gear fitted.

ARK

25.2.13.



© 2021

Lloyd's Register
Foundation

W547-0052