



# Lloyd's Register of British & Foreign Shipping,

3, Steinhoeft,

LLOYDS REGISTER, Hamburg 16th March 1909  
LONDON.

REC'D 18 MAR 1909

*no 1813109*

Sir,

Having reference to the First entry Report No 107188 on the new steamer "B u f f a l o" it will be observed from the Copy of the letter addressed to the Society's Surveyors at Newcastle that the vessel has to be examined in dry dock and indents in the bottom plating be faired, as soon as you have received their Report that these have been attended to this will complete the examination of the vessel for Class.

I have intentionally avoided referring to this in my First entry Report, which please note

I remain, Sir

Your obedient Servant

The Secretary

London

*Geo. Dykes*



© 2021

Lloyd's Register  
Foundation

WS49-0213



Deferred to the Chief Ship Surveyor.

350-442W

MAR 18 1909

London

The Secretary

Your obedient servant

I remain, Sir,

note  
my first entry Report, which please note  
I have unfortunately avoided referring to this in

the examination of the vessel for Class.  
as these have been attended  
by the Report that they have been attended  
by the bottom plating be failed, as soon as  
and incidents in the bottom plating be failed, as soon as  
at Newcastle that the vessel has to be examined in dry dock  
from the copy of the letter addressed to the Society's Surveyors  
the new steamer "Bull" it will be observed  
Having reference to the first entry Report No

Sir,

March 18 1909

3: Stevedore,

principles of the Society's Surveyors

TELEPHONE NO. 1891

1891-1892

Loss above Crown