

1/2 Highland Warrior

Rpt. 6.

For the information of Surveyors and the Committee only.

Received at _____ Office _____ 19

Lloyd's Register of Shipping.

(Report on Vessel No. 40215 Port GLASGOW)

No. 3737 SHIP FORGINGS ~~OR CASTINGS~~.

I have to report that the undermentioned Iron & Steel Forgings or Castings, manufactured by Portland Forge Co. Ltd. of Kilmarnock for the Vessel No. 576, being built by Mess Barclay Curie & Co. of Glasgow have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Rudder top part forged by W. Beattie & Co. Glasgow
12.7.19

The words FORGINGS or CASTINGS, IRON or STEEL, should be struck out as may be required.

Mark on Forgings or Castings.

Lloyd's
No. 3737
JD


Alexander Fletcher & Co
Glasgow

	STERN FRAME.	RUDDER FRAME.	STEM.
Material*	<u>Scrap iron.</u> <u>Forged & built</u> <u>11 3/4 to 9 dia</u> <u>Completed.</u> <u>11.7.19</u>		
How made			
Dimensions			
Progress on Inspection			
Date when Inspected			
CASTINGS.			
Tests on Standard Test Pieces.			
<u>Tensile Test—</u>			
Tons per square inch			
Extension per cent. ...			
<u>Cold Bending Test—</u>			
Angle before fracture			
<u>Drop Test—</u>			
Height from ground ...			
<u>Hammering Test—</u>			
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ NIL (Vessel Classed)

To be paid at _____



© 2021

TCH
10.10.0.0

Lloyd's Register
Foundation

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

1st, 3, 16 T.

Mr Gibbs

W 55-0 236