

COPY.

Lloyd's Register of Shipping.



Port SYDNEY. N.S.W.

20th March 1937.

This is to Certify that I have

Starbd Propeller Shaft

Surveyed the Boilers and Machinery of the T. S. S.

"KAROLA"

of Melbourne,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have Recommended that the record of Boiler Survey 3.37, and Starboard Propeller Shaft Seen 3.37 be made in the Register Book in the case of this vessel.

(SGD) A. J. McCOWAN.

(SGD) E. L. CARTWRIGHT.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
Foundation

WS'S 1 - 0006