

8 OCT 1938 1

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME **ELENCO A. KYDONIEFS**

Rpt. **Ant.**

No. **22232**

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/32.)

DAMAGE.

Survey

age through **grounding**

repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
awed							
oved and faired)							
r repaired.....}							
red or repaired)							
n place.....}							

er items:-

Vessel examined in dry-dock, bottom cleaned & coated
Repairs effected to rudder pintles & bushes, large keels
& minor repairs effected.

s submitted the vessel is worthy to remain as classed with

rd of Survey **9.38**

1004.1.

alter ab. with feed.

9.38. Ant.

W551-0119



© 2021

Lloyd's Register
Foundation
8.10.38