

Steamer "MILLPOOL"  
Owners: Pool Shipping Co.  
Managers: Sir R. Ropner & Co. Ltd.

This vessel was built under the Special Survey of the Society in 1906-10 and was classed #100A1 "Trunk Deck No Sheer". Against her entry in the current edition of the Register Book appears the record "Lost 10,34".


A letter has been received from the West Hartlepool Surveyors enclosing one from Sir R. Ropner & Co. requesting to be furnished with copies of the reports in respect of the 2nd S.S.No.3 held in 1931. The Surveyors state they understand these copies are required in connexion with the inquiry proposed to be held into the cause of the loss in October 1934.

West Hartlepool report No. 17061 which deals with commencement of 2nd S.S.No.3 and damage through striking a submerged object, and Newcastle report No.87646 which deals with completion of 2nd S.S.No.3, have been examined and there would appear to be no objection to copies being furnished at the usual charge.

24.14.6

*[Handwritten signatures]*

1.4.35



© 2021

Lloyd's Register  
Foundation

W556-0106