

Chief Surveyors 15.10.01

Received from Chief Surveyors

S NAME S. S. "Indrasambha"

Report Gls. No. 19303

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

of Survey 1st entry.

When due

± 100A1 ("Steel")

2 Dks (SH) & deep framing.

WB = Cell DBa 113' u & B 56' f 192' 1200t 7PT101t APT50t

FK. 6BH. Cem. Lloyds' A & CP.

Ø 29' B 14.6' F 50'

J. H. D.
15/10/01

C. N. J.



© 2021

Lloyd's Register
Foundation

WTSR-0141