

Ship Surveyor .....

Received from Chief Ship Surveyor

20 JUN 1904

1E

"CARRIGAN HEAD"

Rpt.

Bel

No. 11313

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 3rd S.S. No.2, due 4,33, has been partly held.

The Belfast Surveyors now report the vessel examined afloat  
Special Survey completed.

A fracture was found in tank top of deep tank starboard side  
end, but this repair has not been proceeded with as the Owners state the  
has been sold for breaking up purposes, to Metal Industries Ltd., Rosyth.


It is submitted a record of "To be broken up" be inserted in  
Register Book.

It is further submitted the Leith Surveyors be informed of the  
and requested to advise this Office when the work of demolition has been  
completed.

W561-0086

19.6

©2021



Lloyd's Register  
Foundation