

dated by Chief Ship Surveyor 30.8.06

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME St. Steam Trawler "Seyon" Rpt. Hull No. 18287

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/02.)

Signature of Surveyor Init duty

It is submitted that before this case receives the consideration of the Committee the Grimsby Surveyors should be requested to ascertain by letter from the Owners whether they are willing to accept the hawsers supplied to this vessel, they being 5½" and 4" respectively in lieu of 6" and 5" as required by Table 22.

Dr Gms 30.8.06.

C. A. J.  
30/8/06



© 2020

Lloyd's Register  
Foundation

W563-0266