

Lloyd's Register of Shipping.

201, Tower Building,

Liverpool, 3rd March 1921.

Ans'd.

9/3/21

Dear Mr White,

With reference to Supplement No.17 received here this morning I notice in the list of Owners whose names are not already recorded in the Register Book an entry for R. Neill & Sons, Ltd, Bangor, N. Wales. I think the address in this case should be Bangor, Co Down and thought it well to drop you a line privately so that the address can be verified.

At the same time I might mention it has been pointed out that the S.S. IMPERATOR " has eight steam turbines whilst the Register Book shows four.

With kindest regards.,

Yours faithfully.

C. H. S. White, Esq.

LONDON.E.C.



© 2020


Lloyd's Register
Foundation

Expenses (if chargeable) £
Surveyor's Fee (if any) £

21.11.10
Surveyor to Lloyd's
THE JAN 4 1923

Submitted The correct record should be
of Steam Turbines paid by a screw shaft

~~1987~~
~~11-3-21~~



© 2020

Lloyd's Register
Foundation