

Encl 10562.

Limit on screw shaft lines expired 12. 17.

The Grimsby Surveyor states the  
perintendent has been in communication  
with the Liverpool Surveyors with a  
view to limit on screw shaft lines  
being extended. (See back of report.)

Submitted the Liverpool Surveyors  
requested to state what has been  
arranged in the matter.

T.J.S.

20.2.18.



© 2021

W574-0160

Lloyd's Register  
Foundation