



L31.

4E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME s.s. "BORELIS"

Rpt. Singapore No. 4909

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

re of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The class is subject to the donkey boiler not being used and to the uptakes being repaired at the Special Survey.

A general examination has now been carried out by the Singapore Surveyor with a view to the vessel proceeding to Japan where she is to be broken up.

IT IS SUBMITTED action be deferred.

28.7.31



© 2021

Lloyd's Register  
Foundation