

F.E.

Received by Chief Ship Surveyor 13.7.03

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Sgt. S.S. "Clan Macintyre" Report Apr. No. 12124

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

| Items.   | Additions (if any) required by Rules, or as approved. | On account of:—            |
|--|---|----------------------------|
| Main Sheerstrake . .   | <u>6/20"</u>  | <u>Proportions &amp;c.</u> |
| Spar Sheerstrake . .   | <u>✓</u>  | <u>✓</u>                   |
| Description of Framing:— <u>Deep framing as approved.</u><br>(viz., ordinary, deep, zed, channel or bulb-angle). |   |                            |

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\nabla 100A1$  ("Steel") as recommended.

 $\nabla 100A1$  ("Steel")2 DR (Stl) & deep framingM.B = Cell DB = 117' u E & B 63' f 167' 1040t DT f 31' 808t APT 21tFK 68H Cum. Length 147' CP P39' B 111' F 40'

P. H. P.  
© 2021/03

Lloyd's Register  
Foundation