

VEYORS

IO. BW 7023
OX 338 F

Lloyd's Register of Shipping.

4 BRIDGE STREET,

LOD'S REGISTER
RECEIVED

14 AUG 1933

LONDON

SYDNEY, 7th July 1933.

N.S.W.

The Secretary,

Sir,

The Steel Screw Steam Collier
"CHRISTINA FRASER" of Sydney N.S.W. has now been
given up as lost with a crew of seventeen hands.

The vessel left Bulli N.S.W. with a full
cargo of coal about 8 P.M. on the 22nd June 1933
for Geelong, Victoria, and when off Gabo ran into
cyclonic weather and has not since been heard of.

She was last seen hove to off Gabo at 1.50
A.M. on the 24th June 1933 by the steamer "Koranui",
who reported that both vessels were then hove to in
very heavy weather.

So far as we are concerned, this vessel was
good and sound in all respects, this I told the Deputy
Director of Navigation who asked me the question,
vessel being in our class.

No wireless was fitted.

See Press cuttings attached.

I am, Sir,

Your obedient Servant,

A. C. Heron

W580-0192



Lloyd's Register
Foundation

Received by me,

19

(if chargeable)

Overtime fee

Surveyor to Lloyd's

Referred to Mr. Dyers

02

Referred to Mr. Dyers

E

Mr. Powell

14 AUG 1933



© 2020

Lloyd's Register
Foundation

BYORS
EW 7023
1338 F