

BENMACDHUI

F.E.

Received by Chief Ship Surveyor 7.7.02

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Sea. S.S. "Comet" Report \_\_\_\_\_ No. \_\_\_\_\_

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>1/20" bul, but shelter</u>	<u>deep sides increased</u>
Spar Sheerstrake . .	<u>"</u>	<u>"</u>
Description of Framing:— <u>Bulb angle</u> . (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A1 ("Steel") "Shelter bulk" as recommended.

 $\pm$  100A1 ("Steel") "Shelter bulk"

2 DR. (Sec) 3 to B + shelter DR (Sec)

M. B = Cell DBa 127' x EYB 69' f 148' 908t DTa 29' 869t DTf 25' 790t FPT 77 APT 46t

FK 6BH Cas. Lloyd's A &amp; CP.

C.H. J.  
7/7/02

© 2021

Lloyd's Register  
Foundation

W582-0116