

Undertaking case

17 SEP 1934

Chief Surveyors 14.9.34

Received from Chief Surveyors

VESSEL'S NAME Stt 4p Comte de Flandre

Report Ant

No. ¹⁸⁹⁹³
~~17678~~

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

Year of Survey 2nd S.S. No 3

When due 7.31

? General Examination

BS due 8.31
IS due 1.33

The class is subject to the outer plates, repaired by electric welding 5,31, being specially examined at the next drydocking.

The 2nd S.S.No.3 became due 7,31 and no part of the survey has been held.

The vessel being laid up, the Owners have furnished the usual undertaking.

The vessel was generally examined in August, 1933, and found satisfactory, the Special Survey being then more than two years' overdue.

In reply to enquiry the Antwerp Surveyors state that the vessel is still laid up.

The year of grace expired 7,32.

It is submitted for the consideration of the Committee whether action might not be deferred.



© 2020
Lloyd's Register
Foundation
17.9.34

W585-0127