

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME *Argonauta*

Rpt. No. *7427*

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92)

Particulars of Survey

~~DAMAGE~~ WEAR AND TEAR.

Repairs effected to various furnaces in port & Starboard main boiler

When submitted the vessel is eligible to remain as classed with out fresh.

Particulars of Survey

as recommended. Subject to :-

- port boiler - Centre furnace*
- Star " - port furnace*
- aft " - Star furnace & circumferential*
- Beam (aft port side).*

being specially examined at vessel B.S.

*J. H. M.
6. 8. 31*



© 2021 Lloyd's Register Foundation

WS87-0006