

total capacity tons. FPT tons; APT
N.B.—All alterations in the existing records should be underlined.

CHARACTER.
* For Special Survey, try and of Barveys.

LINE NO.
1880

ON ADMIRALTY LIST.

TELEGRAPHIC ADDRESS
"REGULATOR, LIVERPOOL"

RAYSON, ROLLO & CLOVER DOCKS LTD.

SHIP REPAIRERS AND ENGINEERS

ORS,
N. ST., K. B. E.,
CHAIRMAN
N. VICE-CHAIRMAN.
LLO, C. M. G., D. S. O.,
MANAGING DIRECTOR.
ON
E. E., BT.

WORKS
LIVERPOOL
NORTH - SANDHILLS
SOUTH - QUEENS DOCK
GARSTON
DALE STREET



WORKS
BIRKENHEAD
SIX PRIVATE DRY DOCKS
226 FEET TO 570 FEET
TWIN SCREW OIL
SEPARATING BARGE

LONDON REPRESENTATIVE AT
16, ST. HELENS PLACE, E.C.3.
TELE. NO. AVENUE 5849.

HEAD OFFICE
SANDHILLS

LIVERPOOL, 20. 3rd. March 1934.

The Principal Surveyor,
Lloyd's Register of Shipping,
Tower Building,
LIVERPOOL.

Dear Sir,

s.s. "SAN EDUARDO".

We shall be obliged if you will kindly arrange for a Surveyor to attend the above vessel at Stanlow, to-morrow, Sunday, the 4th. inst. at 11 o'clock to examine the ship internally with a view to putting her through survey.

Thanking you in anticipation,

We are,

Yours faithfully,

For and on behalf of **GRAYSON, ROLLO AND CLOVER DOCKS LIMITED.**

Cecil V. Morgan
Manager Birkenhead Works

JGD/FG.

Attended 10.30 AM to 4 P.M.

G. L. Hughes




© 2020

Lloyd's Register
Foundation

W589-0086

This report is furnished for the information

GRAYSON, ROLLO & CLOVER DOCKS LTD.



© 2020

Lloyd's Register
Foundation

of the
girdle
La
(Peri
on
an
re
st
In da
of
REP
If so, is the Report sent now, or when will it be sent?
SUMMA
B
B
P
PRESEN
Decks ...
Gaulking
Coaming
Beams &
Outside I
"
Breastho
Transoms
Frames
Reverse I
Longitudi
Transvers
Floors ...
Keelsons
Stringers
Inner Bot
Gen
th
su