

1m, 12, 20.

Presented to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steek S.S. "SWIFTEAGLE" Report Pld. No. 632**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

\* 100 A.1. (steek) "Shelter Deck with freeboard"

"Carrying Petroleum in bulk"

2 Dks (steek) \* Shelter Deck (steek). \* Webframes. Longitudinal Framing.

Cell DB &amp; EYB 71' 230t. DT &amp; SD' 444t. Tween Dk tanks a. 30t. FPT 183t. APT 31t.

FK. 17 BH. (3 to Shelter Dk. 10 to Upper Dk. 4 to 2<sup>nd</sup> Dk) p/ceem. A.Y.C.P.

Mchy. Aft.

6/21  
It is included the thickness of the floors in the boiler space are as approved, that the channel shelter deck side transverse 9" H bar bottom longitudinal forward are 40lb & 60lb weight per foot respectively that the scantlings of the lower side transverse at ends are as approved, but the Surveyors should be requested to state if this is so.

W589-0208