

3-2-20
2-28.

8 JAN 1931

red) as
verified

1000

Calc
into

M. of Wo
on Felt
on, Mont

&c.....

7 ascerta
edges

tter

of

if now r

board)

gth.....

arps

Running

ister Bo
ssed an

ma

21.11.1931

0.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME *St. Lucia "WALMER CASTLE"* Rpt. *P. 82* No. *2005*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey DAMAGE .

Damage through *collision*
(see E.L.N. Rpt 225)

How repaired as follows:-


	Plates	Frames	R. Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed									
Removed and faired									
or repaired									
faired or repaired									
in place									
Other items:-	<i>Vessel examined afloat.</i>								

It is submitted the vessel is worthy to remain as classed with out
record of Survey — as recommended *without special condition.*

As now :- Without it

PLATING to be DRILLED when
vessel is 10 years old,
or at next Special Survey
hereafter.

36



M.A.B.
8.1.31
© 2021

Lloyd's Register
Foundation
W510-0081

Travelling Expenses (if any)
Second Surveyor's Fee (if any)

Surveyor to Lloyd's Register