

COPY.

Lloyd's Register of Shipping.

Port of Port Natal,

December 10th, 1930.

This is to Certify that

ALEXANDER HARGREAVES BOYLE

the undersigned Surveyor to this Society did at the request of the Union-Castle Mail S.S. & Co. Ltd., survey the R.M.S. "Walmer Castle" of London 12546 Tons gross, whilst afloat at Port Natal on the 8th December 1930 and subsequently, for the purpose of ascertaining the nature and extent of the damage stated to have been sustained through a lighter striking the vessel at East London on the 6th December 1930.

On examination the undersigned found No 2 plate of the 3rd strake below the sheer strake on the starboard side indented and holed.

It was recommended that a rivetted doubling plate be fitted over two frame spaces by the width of the plate.

This repair has been efficiently carried out.

A. H. Boyle
Surveyor to Lloyd's Register
of Shipping.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.