

by Chief Ship Surveyor

Received from Chief Ship Surveyor

13 MAY 1921

EL'S NAME *Stal S.T. "GEORGE AUNGER"* Rpt. *Mil* No. *2996*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

The Melford Surveyor reports this vessel has been examined on a Slipway and the requirements of a S.S. N° 3 Carried out
Two plates in the Sheerstrake on the Starboard Side have been renewed, 15 fathoms of chain Cable Supplied and minor repairs effected
A 2nd lower anchor of proper weight and test requires to be Supplied

It is Submitted the vessel appears worthy to remain as classed with record of Survey 5,21 and notation of S.S. Mil N° 3-5,21 Subject to a 2nd lower anchor of proper weight and test being Supplied

100. A.1. "Steam Hauler"
5,21 Mil
S.S. Mil. N° 3-5,21 } Subject etc



2020
11-5-21

Lloyd's Register
Foundation

W503-0041
W503-0042