

Sm, 8, 29.

1

12 FEB '29

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME At L. to 4 Msl. fr "HEREFORDSHIRE" Report Liv. No. 96364

**For the CHIEF SHIP SURVEYOR and ~~SHIP ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey Damage alterations -  
2nd S.S. No 3 When due 1.30

Subject to 15 fathoms of chain cable being  
supplied at the next drydocking

W.F.  
12.12.29

*[Signature]*



© 2020

Lloyd's Register  
W595-0048  
Foundation