

Lloyd's Register of Shipping,

2m, 8, 32.

1

Sent to Chief Surveyors 19. 11. 34

Received from Chief Surveyors 20 NOV 1934

VESSEL'S NAME $\frac{1}{2}$ Dimitrios L. Daniolos Report Ant No. 19410

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey Repairs

When due

DBS due 11. 33

MBB due 9. 34

It is submitted that
this vessel is eligible to
remain as CLASSED.

Laid up

~~Subject to the~~

~~DONKEY BOILER~~

~~not being used again.~~

25/11/34

© 2021



Lloyd's Register
Foundation

W596-0153

J.A.