

Are the butts of Plating, Stringers, &c., properly shifted and strapped? *Yes.*

General Remarks (State quality of workmanship, &c.)

The workmanship throughout is good.

Copy

18377

Compulsory

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port W. Hartlepool When received in London Office

Vessel's Name S/S "Bessborough"

Official No. _____ No. in Reg. Book 72 (Sup)

Port of Registry (For Foreign Vessels) _____

Iron or Steel Steel State whether Classed by Lloyd's Register to be

Name of Owners E.R. Sanderson & Co. Date of Verification 23. 4. 06

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	5	ft.	8½	ins.
From centre of disc to top of statutory deck line at awning or part-awning deck		ft.		ins.
Fresh water line above centre of disc			6½	ins.
Indian Summer line above centre of disc			5	ins.
Winter line below centre of disc			5	ins.
Winter North Atlantic line below centre of disc				ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk.	2	ins.	
			at awning or pt.-awning dk.	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Sgd) J. Thomson Surveyor.

(To be filled up in London Office.)

Statement No. _____ Date of Committee's Minute _____

Moulded Depth for record ft. _____ ins. _____

Freeboards compared and found correct by _____ date _____


Is fee paid? _____ Form for Certificate A

Instructions _____ date _____

Certificate written _____ Noted for posting _____

Jan. 26. T

Classification was Spas Deck conditional on above freeboards



© 2021

Lloyd's Register Foundation

W 596-0164

FRI 4 MAY 1906

Committee's Minute

Character assigned

100871 (See)