

50,8,12.

Mount
Athos

F.E.

Received by Chief Ship Surveyor 26.3.13

Received from Chief Ship Surveyor


VESSEL'S NAME *Steelss "Lassifoglu"*Rpt. *SLs*No. *25632*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *74.75*Depth "d" *21.54*Framing: Table No. *3 page 15*Description *Bulb angle as approved*Longitudinal No. *26162*Proportions Length = *1068*
Depth*Bridge Deck Sheerstrake as approved.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100 A-1. (Steel)* as recommended.

*100 A-1. (Steel) as recommended.**1 Dk (steel)**WB = Cell & B a 10'8", u & 23' f 150 952 L, FPT 105 L, APT 144 L**FK. 6 Bk. Cam' Lloyd a x c p. P 35. B 240, F 36'*Lloyd's Register
Foundation

1860-0092

CBS

50

Toe Bulb, or Channel

Angles on upper edge

Angle on ditto

Tie Plates

4 1/2 x 4 1/2