



Am. 1.31.

2E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME s.s. "SCALA SHELL"

Rpt. Hong Kong

No. 6676

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Result of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. *S.S. No 2*

This Survey, due 3,30 partly held at 8,30 ON ENGINES now completed, and the following repairs carried out (due to ~~the~~)

Starboard M.P. piston renewed, patch fitted to port M.P. cylinder.

Electric wiring partly renewed and minor repairs effected.

BS due 1,31 now held.

It is submitted the vessel is eligible to remain as classed, with
condition of *MLMC* MS 8,30
BS 3,31
as recommended.

CB.

6.5.31.



© 2020

Lloyd's Register
Foundation

W601-0246