

Chief Surveyors 17.3.02

Received from Chief Surveyors

SHIP'S NAME S.S. Bk. "Urania"

Report Sl. No. 19699

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey First entry

When due

It is submitted that the Glasgow Surveyors be requested to state whether the record of decks on the third page of their report is correctly stated, in view of the particulars on the first page showing a lower deck to have been laid as shown on the approved midship section. Under the circumstances it appears that the record of decks as it should appear in the Register Book is "2 Dks (U Sec - WS) & deep framing."

It should at the same time be pointed out to them that the record of decks on the third page of their report on the S.S. "Surada" is not as it should appear in the Register Book. It should have been stated thus:— "2 Dks (Sec - U WS at Seal) 3 to B & web frames."

The first entry reports on these vessels should be returned to the Surveyors for correction in regard to the above.

L. H. H. L. H.
27.3.02

W/601-0332



© 2020

Lloyd's Register
Foundation
12/3/02