

by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor **11 AUG 1934**

EL'S NAME *St. Tw. Sc. RUY BARBOSA* Rpt. *Hamb.* No. *21236*

**Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey \_\_\_\_\_

The *Hamburg* Surveyors report this vessel placed in dry dock, bottom cleaned and coated and ~~minor~~ repairs effected to a fractured shell plate.

It is submitted the vessel appears worthy to remain as classed with record of survey *7.34* as recommended.

*100 A.1*  
*with freeboard*  
*7.34 Ham*

*[Signature]*  
*10.8.34*

