



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 26th September 1935.

LLOYD'S REGISTER
RECEIVED
27 SEP 1935
Vnsd. 279
LONDON

Reference

M. Dear Sir,

With reference to your letter of the 18th instant, regarding the case of the S. S. "LA CRESCENTA", I have to state that the Sunderland Report No. 31000 should be amended as follows:-

"Damage Repairs Effected.

Starboard side "F" strake No.1 plate cropped and part renewed", should read "Port Side "F" strake No.1 plate cropped and part renewed".

I have no notes with reference to the renewal of No.1 plate in F strake, starboard side, nor can I recall to memory any defects in, or repairs, such as those referred to by the Board of Trade, being carried out to, this plate.

I regret the errors in my former reports.

I am, Dear Sir,

Yours faithfully,

M Caldwell

The Secretary,
LONDON.



© 2019

Lloyd's Register
Foundation

W 604-0002

Referred to the Chief Ship Surveyor.

E

27 SEP 1935

Submitted a copy of this letter to
sent to the Specimens of the R.O.Y.

27.9.35



© 2019
Lloyd's Register
Foundation