

COPY.

See Ho R. No 5853

Lloyd's Register of Shipping.



Port SAN FRANCISCO

AUGUST 4th, 1929

This is to Certify *that I have*

Surveyed the Steel Twin Screw Steamer "TAHITI", of London, 7898 tons gross register, while lying in dry dock at this Port on a/c of loosing starboard propeller while making a landing at Pier #33 San Francisco, 6:55½ A.M. August 2nd, 1929 - - - - -

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and


that I have Recommended that she be retained as now classed and have fresh record of survey 8-29, subject to the indented rudder plate being faired at the next dry docking, also to the special Survey 2nd No.3 being completed and to the indented bottom plating D. & E. strakes port and starboard sides being faired and to the indented shell plate A strake port side aft being faired at the Owner's convenience - - - - -

being fit to carry dry and perishable cargoes.

(sgd) S J READER

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation