

girders, and of the inner bottom plating, especially in the boiler space.

Last Report. No. 32942

Port N. Yk

May 11

+ 100 A  
With feature

SUPERINTENDENT'S DEPARTMENT.

(Please address your reply to the Department and not to individuals)

TELEPHONES.  
MONUMENT 2525 (9 LINES).

FURNESS, WITHEY & CO. LIMITED,

FURNESS HOUSE,

LEADENHALL STREET,

LONDON, E.C.3.

16 DEC 1931

15th December, 1931.

The Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street,  
E.C. 3.

Dear Sir,

M.V. "BERMUDA".

With reference to your letter of the 14th inst., the final position in regard to this vessel has not yet been determined, and we shall therefore be glad if you can leave the question of expunging her name from the Register open for the time being.

Yours faithfully,  
For FURNESS, WITHEY & CO. Limited,

Chief Superintendent.

The writers of this letter now refer the Society to the Salvage Association who state, in reply to enquiry by telephone, that they will be glad if the Committee will again defer action for the present as the matter is not yet settled but can be seen referred before 7.15.12 to the Underwriters at C.T.B., which is confirmed by Lloyd's (per Mr. Belmont)

27/1/32

© 2020

68238

Lloyd's Register  
Foundation

W606-0038



Referred to Mr. Bishop.

*Handwritten signature*

*Handwritten signature*

16 DEC 1931



© 2020

Lloyd's Register  
Foundation