





107 boilers (two two ton type) have been renewed. On account of  
the condition of the remaining furnaces in the 18 boilers it  
has been arranged to renew these also, and this will be  
done at St. Andrew's where work will be reconditioned.  
The Main boiler Mountings have been examined and  
repacked.

J. J. Miller

N.B. - If this Report is copied by Coping Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation