

S.S. "ESSEX ABBEY".  
-----

In reply to enquiry over the telephone today the Owners stated that the donkey boiler now on board had been condemned by them and would not be used again. They were negotiating for a new donkey boiler, which they hoped to have fitted on the vessel's return from her present voyage to Sierra Leone.

*Recd.*  
5.5.32.



Lloyd's Register  
Foundation

W618-0150