

(3m, 6, 4.)

Received by Chief Ship Surveyor 22.9.04

Received from Chief Ship Surveyor

VESSEL'S NAME SS. S.S. "Rugbeian" Report Rugbeian No. 47637

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey

First entry

It is submitted that before this case receives the consideration of the Committee the first entry report should be returned to the Surveyors who should be informed that the class of this vessel should be * 100A1 Spar deck with freeboard, and not as stated on their report, and they should be requested to rectify the same. They should at the same time be requested to obtain and forward to this Office a letter from the Owners consenting to the omission of ceiling from the holds.

In Sept 6 Rwc
22/9/04

C. H. P.
22/9/04

Owners letter
approving ceiling
on Rwc &
under Rwc



© 2019

Lloyd's Register
Foundation